ure of manufacture, the ceramic sink surface is not perfectly flat tly flat Basket Strainer Installation. k surface is not perfectly flat

INSTALLING A BASKET STRAINER WASTE ON A CERAMIC SINK

Due to the nature of manufacture, the ceramic sink surface is not perfectly flat, care should be taken to ensure a good seal between the top surface of the sink and the waste kit. A good bead of suitable silicone or Plumber's Mait for example.



 The image above shows the location of the required seal, it is important that an ample amount of sealant is used to ensure there are no small air bubbles or gaps which could allow a small amount of water to trickle through.



 The image above is to help confirm the location of the sealant, the seal is between the top of the ceramic sink and base of the steel "cup".



 The image above is to help confirm the location of the sealant, the seal is between the top of the ceramic sink and base of the steel "cup".